PRINTED: 08/27/2012 FORM APPROVED OMB NO. 0938-0391

CENTERS FOR	R MEDICARE & MEDIC	CAID SERVICES				OM	IB NO. 0938-0391
STATEMEN	T OF DEFICIENCIES	X1) PROVIDER/SUPPLIER/CLIA	(X2) M	ULTIPLE (CONSTRUCTION	(X3) DATE	SURVEY
AND PLAN OF CORRECTION IDENTIFICATION NUMBER: 155298		IDENTIFICATION NUMBER:	A DUIL DING 01			COMPI	LETED
		A. BUILDING			08/08	/2012	
		<u> </u>	B. WIN		TADDRESS CITY STATE ZID CORE		
NAME OF I	PROVIDER OR SUPPLIEF	R			T ADDRESS, CITY, STATE, ZIP CODE		
0444001		01N 0 0 DELLA DILITATION OFNI			TOWNSHIP LINE RD		
CAMBRI	DGE MANOR NUR	SING & REHABILITATION CEN	IER	INDIA	NAPOLIS, IN 46260		
(X4) ID	SUMMARY S	TATEMENT OF DEFICIENCIES		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	(EACH DEFICIEN	NCY MUST BE PERCEDED BY FULL	PREFIX		(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI	ATE	COMPLETION
TAG	REGULATORY OR LSC IDENTIFYING INFORMATION)		TAG		DEFICIENCY)	AIE.	DATE
K0000							
	A Quality Assurance Walk-thru Survey was conducted by the Indiana State		K0000				
	Department of H	Iealth.					
	Survey Date: 08	3/08/12					
	Facility Number	000105					
	Provider Number: 155298						
	AIM Number: 1	100267690					
	Surveyor: Mark Caraher, Life Safety Code Specialist						
	Code Specialist						
	A (1 : O 1 :)	X X 11 .1					
		Assurance Walk-thru					
	survey, Cambrid	lge Manor Nursing &					
	Rehabilitation C	enter was found not in					
	compliance with	with 410 IAC					
	16.2-3.1-19(ff).						
	10.2 3.1 17(11).						
	This there a start	£- ::1:4					
	1	facility was determined to					
		22) construction and fully					
	sprinklered. The	e facility has a fire alarm					
	system with smo	oke detection in the					
	l -	all areas not separated					
		r. The facility does not					
		ectors in resident sleeping					
		lity has a capacity of 135					
	and had a census of 67 at the time of this visit.						
	The facility was	found in compliance with					
	I	_					
	i state law in rega	rd to sprinkler coverage	- 1				

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

000195

(X6) DATE

Any defiency statement ending with an asterisk (*) denotes a deficency which the institution may be excused from correcting providing it is determined that other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/27/2012 FORM APPROVED OMB NO. 0938-0391

	OF CORRECTION OF CORRECTION 155298	(X2) MULTIPLE CO A. BUILDING B. WING	01	(X3) DATE SURVEY COMPLETED 08/08/2012
CAMBRI	PROVIDER OR SUPPLIER DGE MANOR NURSING & REHABILITATION CENTE	8530 To	ADDRESS, CITY, STATE, ZIP CODE OWNSHIP LINE RD IAPOLIS, IN 46260	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PERCEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPE DEFICIENCY)	E COMPLETION
	and was found not in compliance with state law in regard to smoke detector coverage.			
	All areas where residents have customary access were sprinklered. The facility has two detached storage buildings providing facility services such as storage which were not sprinklered. Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 08/10/12. The facility was found not in compliance with the aforementioned regulatory requirements as evidenced by the following:			

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: 3KWK21

Facility ID: 000195

If continuation sheet

Page 2 of 4

PRINTED: 08/27/2012 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY		
AND PLAN OF CORRECTION		IDENTIFICATION NUMBER:	A. BUILDING		01	COMPLETED	
	155298		B. WING			08/08/2012	
			B. WIIV	_	ADDRESS, CITY, STATE, ZIP CODE		
NAME OF P	PROVIDER OR SUPPLIER				OWNSHIP LINE RD		
CAMBRIDGE MANOR NURSING & REHABILITATION CENTE			ER		IAPOLIS, IN 46260		
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIES		ID		PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	(EACH DEFICIENCY MUST BE PERCEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		PREFIX TAG		(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATION OF THE APPROPRIATION	TE.	COMPLETION
TAG					DEFICIENCY)	_	DATE
K9999							
	State Findings		K9999		K9999: This serves as the		09/07/2012
					allegations of conpliance for		
	3.1-19 ENVIRO	NIMENIT AND			Cambridge Health Care Center. Cambridge Health Care Center		
	PHYSICAL STANDARDS 3.1-19(ff) A health facility licensed under				aserts that all corrections		
					described on this Plan of		
					Correction have been		
	16-28 and this ru	le must do the following:			implemented. In regards to the specific deficiencies, we have		
	(1) Have an automatic sprinkler system installed throughout the facility before July 1, 2012.				outlined our corrective actions and continued interventions to		
					assure compliance with regula		
					and our plan of actions. The staff		
	` '	ic sprinkler system is not			of Cambridge Health Care		
	installed through	out the health care			\Center is committed to deliver	ing	
	facility before Ju	ly 1, 2010, submit before			high quality healthcare to its		
	July 1, 2010 a plan to the department for completing the installation of the				residents to obtain their highes	st	
					level of physical, mental and		
		ler system before July 1,			psychosocial functioning. We		
	2012.	ier system before sury 1,			respectfully submitthat Cambridge Health Care Cente	r ie	
		. 1 1 1 1 1			in substantial compliance as se		
	(3) Have a battery operated or hard-wired smoke detector in each resident's room before July 1, 2012.				forth below, and we are confidence		
					that we will be found to be in		
					substantial compliance with		
					regulations upon resurvey. Th	е	
	This State Rule h	nas not been met as			statements made on the Plan		
	evidenced by:				Correction are not an admission	n	
	1	ation and interview, the			to and do not constitute an		
					agreement with the alleged	th.	
	1	install smoke detectors in			deficiencies. Cambridge Healt Care Center has completed the		
		sleeping rooms before			following interventions as a res		
	-	is deficient practice			of the findings from survey exit		
	could affect 67 residents in the facility.				on 8/8/12. *What corrective	3	
					action will be accomplished for	t	
	Findings include	indings include:			hose residents found to have		
	Based on observations with the				been affected by the deficiebt		
					practice: *The facility will insta		
					smoke detectors in all resident		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: 3KWK21

Facility ID: 000195

If continuation sheet Page 3 of 4

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/27/2012 FORM APPROVED OMB NO. 0938-0391

AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		ONSTRUCTION 01	(X3) DATE SURVEY COMPLETED	
155298	A. BUILDING B. WING		08/08/2012	
PROVIDER OR SUPPLIER DGE MANOR NURSING & REHABILITATION CENTE SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PERCEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) Maintenance Supervisor during a tour of	8530 T	ADDRESS, CITY, STATE, ZIP CODE OWNSHIP LINE RD IAPOLIS, IN 46260 PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY) Sleeping rooms. *How other	Bille	
the facility from 12:30 p.m. to 1:50 p.m. on 08/08/12, a smoke detector was not installed in each of the 70 resident sleeping rooms in the facility. Based on interview at the time of the observations, the Maintenance Supervisor acknowledged a smoke detector was not installed in any resident sleeping rooms in the facility. 3.1-19(ff)		residents having the potential be affected by the same defici practice will be identified and what corrective action will be taken: *All residents have the potential to be affected. *What measures will be put into place what systemic changes will be made to ensure that the defici practice does not recur: *Smedetectors have been ordered a will be installed by facility maintenance staff in all reside sleeping rooms. *How the corrective action will be monite to ensure the deficient practice will not recur, what quality assurance program will be put into place: *Smoke detectors be installed in all sleeping room by 9/7/12. The smoke detector and batteries will be checked, changed, cleaned and replace according to regulation on goin The smoke detectors, battery check, cleaning, and replacem will be reviewed monthly at the facility QA&A meeting for follo up to assure compliance. *By what date the systemic change will be completed: *Septemb 7, 2012	ent ent ent et eor ent oke and nt ored e will ms ors ed ng. eent e ww	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: 3KWK21

Facility ID: 000195

If continuation sheet

Page 4 of 4